



Description in English of the deliverable:

Set of actual implementation documentations for all restored sub-sites C.1

The document called an „actual implementation documentation“ (dokumentace skutečného provedení in Czech, abbrev. DSP) is a summary document describing the real situation at the restored site – description of the affected area, implemented measures – number of woody dams, length of restored streams etc.

At the end, there is a conclusion summarizing all the information relevant for the restored site – the total number of infilled channels and the total number of restored streams. If relevant, it might also mention the deviations between the initial proposal of restoration measures in the project documentation and their actual realization. The definite choice of alternative methods or solutions is always justified.

There are 33 documents attached (in total for **32 official project sites + one extra site**, Mlynářská slať, which was chosen as a complementary site for the site Raskov; Raskov site was not allowed to be restored in its totality due to the refusal of the energy company eg.d, as due to the restoration, the site was supposed to become wetter which limited or even prevented access to the electricity distribution company eg.d in case of emergencies or regular inspections of the electrical wiring).